

Abstract

A method for digital data transmission from a sensor (PPS) to a control unit (SG) is described, the sensor values of the sensor (PPS) being divided for data transmission at different resolutions. The sensor values form a first range of values including successive
5 sensor values. The first range of values for data transmission is divided as a function of a variable relevant for the control unit (SG).

(Figure 1)